

## **Building Consistency Meeting**

Commercial

Date 7/01/2015 Recorder and minutes prepared by: Jay E. Garbus/Lon McSwain

<b>Staff present</b> : On File	
Public present:	

- 1) Separation of exterior exit stairs Need to check travel distance and will need to be separated.
- 2) How to measure travel distance Need to measure with furniture in room.
- 3) How much of an opening is required from a mezzanine to the floor below There is nothing in the Code but needs to be the width of a stair open 44".
- 4) Section 805.2 Exception 2 of the 2015 Existing Building Code on rated corridors, and exit separation Can leave it the way it was and does not create a higher hazard does not need to be rated.
  - **805.1 Scope.** The requirements of this section shall be limited to work areas that include exits or corridors shared by more than one tenant within the *work area* in which Level 2 *alterations* are being performed, and where specified they shall apply throughout the floor on which the *work areas* are located or otherwise beyond the *work area*.
  - **805.2 General.** The means of egress shall comply with the requirements of this section. **Exceptions:**
  - 2. Means of egress conforming to the requirements of the building code under which the building was constructed shall be considered compliant means of egress if, in the opinion of the *code official*, they do not constitute a distinct hazard to life.
- 5) Repairs made under Chapter 6 of the 2015 Existing Building Code Need to back to the way it was built. Cannot make it worse than it was.
  - **601.1 Scope.** Repairs as described in Section 502 shall comply with the requirements of this chapter. Repairs to *historic buildings* need only comply with Chapter 12.
  - **601.2 Conformance.** The work shall not make the building less conforming than it was before the *repair* was undertaken.
- 6) Pool gate hardware when occupant load is over 100 Need panic bar if they have bar, entertainment and other uses other than pool only.

## WE STRIVE TO PROVIDE EXCELLENT PLAN REVIEW AND INSPECTIONS WITH OUTSTANDING CUSTOMER SERVICE

Approved By	Lon McSwain	Date 07/10/2015